

# TURBO-CHARGED COMPONENTS



**NEW VALVE HOUSING. INCLUDED!!**

**ON HAND**



## Wastegate

Includes all of the following series: 470908,481064, 470818,470954,470842,481036. Overhaul with new Gate assemblies.Units with serviceable gate offered at lower prices when available.  
Price:\$790.00

Type:Exchange/Overhaul

Core Charge: \$400.00

## Pressure Relief Valves

470930 Series, 470944 Series & 481028 Series. Most units in stock for exchange. We can overhaul your unit same day if needed.

Price: \$390.00

Type: Exchange/Overhaul

Core Charge: \$400.00

## Turbochargers

Full line of Turbochargers. Overhauls, factory new, and factory overhaul units available. Please call for prices, availability and core charges.

Price: Call For Quote

Order #: Consult OEM manual

Type: Exchange, Overhaul & Factory New

Core Charge: Call

## Oil Seal Assembly

Repair per FAA Repair Specification on oil seal for the Rajay Turbochargers.

Price: 235.00

Order #: 600369

Type: Repair—Exchange only.

Core Charge: \$100.00

## Wastegate Valve Assemblies

PM477240-0/ \$340.00; PM477240-5/ \$325.00;

PM477240-3 & -4 / \$295.00; 478160-1 /\$340.00

Housings, shafts butterflys,bushings are sold Separately.

Housings: PM476927-2, PM476927-4,

PM477542-1 & -2, PM478158-1 \$225.00 ea

Butterflies: PM477150 \$69.00,PM477237-1 \$61.00

PM477242 \$60.00

Bushings:PM476130-3 \$35.00

\*\*\*\*\*KITS\*\*\*\*\*

PM064, PM780, PM818, PM908, PM954

1 Shaft+2 Bushings+1Butterfly+ 1 Groove Pin,

2 Retainer Rings for \$185.00 ea.

## Boot Bellows

Repair to part Numbers 476226 -0001, 0002, and 0003 per FAA Approved Process Spec

Price \$325.00 (476226-0002 &-0003 each)

Price \$325.00 (476226-0001 & -0004 each)

Type Repair

Core Charge \$100.00

Email => [rob@arizonaaircraft.com](mailto:rob@arizonaaircraft.com)



## Controllers

All Series. Exchange units available or same day turn of your unit.

Price: \$790.00 (All Series Except Dual Controllers)

Price: \$1,190.00 (470782, 470948 & 470934)

Order #: Consult OEM manual for part no.

Type: Exchange/Overhaul

Core Charge: \$400.00 All series except Dual Controllers

Core Charge: \$550.00 (470 782,470948 & 470934)

## We also carry:

### U-CUP

FAA approved PMA replacement part for OEM part no. 476884-0002 Priced at \$37.50 Each  
Order # PM476884-2



### Rear Bearing Kit

FAA approved PMA replacement part for OEM part no.# 90-2014—Priced at \$42.00each (Qty's 1-9) , \$37.00 Each (Qty's 10 +). Order # PM90-2014

## NEW ITEMS

**TURBINE HOUSING PM 406722-21**

**\$450.00 each & AVAILABLE**

**CENTER HOUSING PM 441320-4,-5, -6**

**\$200.00 each & AVAILABLE**

**Brgs. PM 407134 @ \$ 13.75 ea**

**Brgs. PM 404922 @ \$ 13.75ea**

**ON HAND**



**ON HAND**



**ON HAND**

